

Repair of Dryvit Outsulation Exterior Insulation Finishing System (EIFS); Spec #42-09/20			
	Please note, the amounts shown are the numbers that were read at the public bid opening and do not reflect any evaluation and do not indicate an intent to award.		
	All vendors listed below have been checked against the PA Department of General Services Debarment List and none are listed on the day of the bid opening.		
Reference Number	Description	Diamond Design Construction Inc	Jones masonry restoration corp
1	Repair of Dryvit Outsulation system in specified locations	\$39,770.00	\$175,000.00